

1345Z 02 NOV 62

S E C R E T

C/DD

M/D

G/D

II

CD

RB

25X1

DIRECTOR

ZESI9D

ROUTINE

OSA (✓-2-3-4-5-6-7-8-9-10)

S/C (11)

25X1

TOR 1345Z 02 NOV 62

25X1

ROUTINE

IN 54279

TO

INFO

SITE

25X1

25X1

25X1 SINCE [REDACTED] REPORT 1132, (IN 54058) THE STATUS CHANGES OF FIELD OPERATIONS ARE AS FOLLOWS:

1. 201 STATUS UNCHANGED.
2. 202 AND 203 DISASSEMBLY HAS STARTED AT [REDACTED]
3. 204 IS ON THE STAND. EXPECT TO BE ABLE TO RUN LATE THIS AFTERNOON ON TT4 AND TT5 CORRELATION CHECKS.
4. 205 IN 121 REMAINS AVAILABLE FOR NEXT GO. MIN FLOW HAS BEEN SET UP IN ORDER TO INCREASE PRESSURE FOR ACTUATION OF CIS UNIT. MORE DETAILED INFORMATION HAS BEEN SUPPLIED TO THE FIELD FOR GUIDANCE IN OPERATION DURING RELIGHT PROCEDURE.
5. NBR 123 HAD SUCCESSFUL FLIGHT WITH 475°'S. NO ENGINE PROBLEMS. NEXT GO PLANNED FOR TOMORROW, 11/2.

END OF MESSAGE

S E C R E T